

Release Notes – SPR 26639 – MC91, MC31, MC92, MC32, WT41: DATAWEDGE ERROR

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

SPR 26639– MC91, MC31, MC92, MC32, WT41- Datawedge application doesn't reconnect after 10 min inactivity disconnection.

Description

The new version of DW - DATAWEDGE_3_6_16_140409 works as expected, once the scanner is awoken, DW turns immediately to Ready

Contents

DataWedgev3.6.16.CAB

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC91,MC31	CE 6
MC92,MC32	CE 7
WT41	CE 7

Installation Requirements

n/a

Installation Instructions

1. Copy xxx.cab to the device and install it

2. Copy xxx.cab file to the device and install it
3. Reboot device

Part Number and Release Date

n/a

December, 2014.